

AD ORIENTEM

IGREJA DO SALVADOR DE CABEÇA SANTA

DIMENSIONS OF THE SPACE

Nave - Length - 11.83m / Width - 5.95m / Height - 8.56m

Presbytery - Length - 6.19m / Width - 4.26m / Height - 5.83m

ACCESS DIMENSIONS

Door 1 (front) - Width - 1.46m / Height - 3m

Door 2 - (side) - Width - 1.07m / Height - 2.26m

Door 3 - (sacristy) - Width - 1m / Height - 2m

ACCESS CHARACTERISTICS

Distance from parking to doors - 5m

Type of access - Flat and accessible

PERFORMING AREAS (PA)

Area 1 (Presbytery)

Dimensions - Length - 3m / Width - 3.25m

Distance from the center to the audience - 3.0m

Distance to the control area (Recording) - 2.0m

Materials - Granite

Fixed Furniture - Altar

Produção:



CARDO

Apoios:



dgARTES
DIREÇÃO-GERAL
DAS ARTES



AD ORIENTEM

Area 2 (Nave)

Dimensions - Length - 3m / Width - 5.9m

Distance from the center of this to the audience - 1.5m

Distance to the control area (Recording) - 5m

Materials - Granite and wood

Fixed Furniture - None

SEATING CAPACITY

Seating capacity - 90 people

Audience visibility of performance areas - Good, with no obstacles in between

FURNITURE

Organ or instruments present - Yes, located at the back of the church

Condition - Functional

Possibility of use - yes

Accessible furniture for loan - 10 benches and 3 chairs

LIGHTING

Sufficient lighting for musical performance - No

Presence of sonic characteristics from lighting - None

Approximate color temperature - Warm color

OTHER SCENIC SPACES

None

Produção:



CARDO

Apoios:



dgARTES
DIREÇÃO-GERAL
DAS ARTES



AD ORIENTEM

CONTROL AREA (Recording Room - Sacristy)

Dimensions - Length - 2m / Width - 2m

Distance from performance areas - 3m and 5m

Presence of power outlets - Yes

SECONDARY STORAGE SPACES

Dimensions - Only in the sacristy, possibly in the parish house

Distance to performance areas - 5m and 25m

DRESSING ROOM

Number - None

Dimensions - N/A

TOILETS

Location: Outside, in the parish house

Number of toilets - 2

Presence of a shower - No

Presence of a mirror - Yes

Distance and access to PA - 25m

Produção:



CARDO

Apoios:



dgARTES
DIREÇÃO-GERAL
DAS ARTES



AD ORIENTEM

GENERAL STATE OF CONSERVATION

Score 0/10 - 7

Windows and doors (insulation and sturdiness) - Insufficient insulation;
cracks in doors

Presence of vestibules at access doors: No

Finishes and coverings - Granite and wood

Ceiling characteristics - Wooden with a pitched structure

Construction period and style(s) - Romanesque

ELECTRICITY

Ground connection - Yes

Three-phase electricity - No

Location of power outlets - 2In the sacristy and on both sides of the nave
and presbytery

Produção:



CARDO

Apoios:



dgARTES DIREÇÃO-GERAL
DAS ARTES

